

STAGE ON
ARE PARTS

eparately

Part	Postage
...	2d.
...	2d.
...	4d.
...	3d.
...	6d.
...	4d.
...	6d.
...	6d.
...	3d.
...	2d.
...	4d.

PTS.

lantle which has a hole
y break the Globe.

without using the Oil

more than about half

fin. If you do, the
ast so long.

too soon. Read very
titled "Preheating by

e life of the Vapouriser
to the vapour hole—
matters.



BRITISH MADE THROUGHOUT

INSTRUCTION BOOK

WITH LIST OF SPARE PARTS



Including Notes on possible
difficulties and how to
overcome them.

Manufactured throughout by

The
TILLEY LAMP CO.
HENDON · LONDON N.W.4 · ENGLAND